

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	5 April 2016
Time:	14:00
Inspection No.:	125

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> 1. Stagnant water at SA323 was removed. (Closed) 2. Valid NRMM label was provided and affixed on the mentioned roller at SA323. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 3. Mud trails were observed at SA329. The Contractor should remove the mud trails and improve the efficiency of wheel washing. 4. Refuse was observed accumulated on ground at SA328. The Contractor should remove the refuse and provide rubbish bins or skips for easy collection. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Oscar Yip		8 April 2016
Checked by	Y W Fung		8 April 2016

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	14 April 2016
Time:	14:00
Inspection No.:	126

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> 1. Mud trails observed at SA329 was removed. (Closed) 2. Refuse observed at SA328 was removed. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 3. Mud trails and surface runoff was observed at SA329. The Contractor should remove the mud trails and provide proper mitigation measure to prevent surface runoff from entering public road. 4. Stagnant water was observed at SA328. The Contractor should remove the stagnant water to prevent mosquito breeding. 5. Refuse was observed accumulated on ground at SA329. The Contractor should maintain the site in a clean and tidy condition. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Oscar Yip		19 April 2016
Checked by	Y W Fung		19 April 2016

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	19 April 2016
Time:	14:00
Inspection No.:	127

Non-compliance



Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> 1. Mud trail at site entrance of SA329 has been washed. (Closed) 2. Stagnant water observed at SA328 had been removed. (Closed) 3. Construction waste accumulated at SA329 has been properly covered and will be removed off site until new access formed. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 4. Stagnant water was observed in the water tank at NB42. The Contractor should remove the stagnant water to prevent mosquito breeding. 5. Refuse was observed accumulated on ground at NB42A. The Contractor should remove the refuse properly and maintain the site in a clean and tidy condition. 6. Mud trail was observed at NB42A. The contractor should remove the mud trail properly. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Adam Zhu		25 April 2016
Checked by	Y W Fung		25 April 2016

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	27 April 2016
Time:	14:00
Inspection No.:	128

Non-compliance



Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> 1. Stagnant water observed in the water tank at NB42 had been removed. (Closed) 2. Accumulated refuse observed on ground at NB42A had been removed. (Closed) 3. Mud trail observed at NB42A had been cleaned up. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 4. Excavator was observed not provided with proper NRMM label at SA328. The contractor should provide proper NRMM label to the excavator. 5. Stagnant water was observed on ground at SA325. The contractor should remove the stagnant water properly. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Adam Zhu		3 May 2016
Checked by	Y W Fung		3 May 2016