

WIDENING OF TOLO HIGHWAY (STAGE 2)
BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE



Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	3 May 2016
Time:	14:00
Inspection No.:	129

Non-com	pliance
i voii ooiiii	onarioo

Nil

Observations

Follow-up Observation(s)

- 1. Proper NRMM label had been provided to the excavator at SA328. (Closed)
- 2. Stagnant water observed on ground at SA325 had been removed. (Closed)

New Observation(s)

Refuse was found accumulated on ground at SA328. The contractor should remove the refuse 3. properly and keep the site in a tidy and clean condition.

Reminder(s)

Nil.

Remarks

	Name	Signature	Date
Prepared by	Adam Zhu	2.	4 May 2016
Checked by	Y W Fung		4 May 2016



WIDENING OF TOLO HIGHWAY (STAGE 2)
BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE



Site Inspection Summary

Inspection I	nformation
--------------	------------

Contract No.	HY/2012/06	
Date:	10 May 2016	
Time:	14:00	
Inspection No.:	130	

No.	n-co	ıamı	liar	ıce

Nil

Observations

Follow-up Observation(s)

Refuse has been segregated from the construction materials and properly collected and removed. 1. (Closed)

New Observation(s)


3. Mud trail was observed at NB42A. The contractor should remove the mud trail properly.

Reminder(s)

Nil.

Remarks

	Name	Signature	Date
Prepared by	Adam Zhu	10	11 May 2016
Checked by	Y W Fung		11 May 2016



AECOM

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06	
Date:	19 May 2016	
Time:	14:00	
Inspection No.:	131	

Non-compliance

Nil

Observations

Follow-up Observation(s)

1. Mud trail observed at NB42A had been cleaned up. (Closed)

New Observation(s)

- 2. An oil drum without drip tray was observed onsite at NB58. The contractor should provide drip tray to the oil drum properly.
- 3. Mud trail was observed on public road at SA325. The contractor should clean up the mud trail properly.

Reminder(s)

Nil.

Remarks

	Name	Signature	Date
Prepared by	Adam Zhu	7.	20 May 2016
Checked by	Y W Fung		20 May 2016

EM&A Environmental Inspection Record WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE



Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06	
Date:	24 May 2016	
Time:	14:00	
Inspection No.:	132	

No	n-co	mpl	iance
1 401	1 00	HPH	arroc

Nil

Observations

Follow-up Observation(s)

- 1. Drip tray had been provided to the oil drum properly at NB58. (Closed)
- 2. Mud trail observed on public road at SA325 had been cleaned up properly. (Closed)

New Observation(s)


3. Accumulated stagnant water was observed at SA340. The contractor should remove the stagnant water properly to prevent mosquito breeding.

Reminder(s)

Nil.

Remarks

	Name	Signature	Date
Prepared by	Adam Zhu	72.	25 May 2016
Checked by	Y W Fung		25 May 2016



BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

A=COM

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	31 May 2016
Time:	14:00
Inspection No.:	133

A /	
Non-com	pliance

Nil

Observations

Follow-up Observation(s)

1. Stagnant water observed at SA340 had been removed properly. (Closed)

New Observation(s)

- 2. Slurry and mud trail was observed near gully drain at site entrance of SA329. The contractor should clean up the slurry and mud trail properly.
- 3. Oil stains were observed on ground at SA328. The contractor should remove the oil stains properly and provide sufficient measures to prevent oil leakage.

Reminder(s)

Nil.

Remarks

	Name	Signature	Date
Prepared by	Adam Zhu	a.	1 June 2016
Checked by	Y W Fung		1 June 2016