

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	6 March 2018
Time:	13:30
Inspection No.:	225

Non-compliance

Nil

Observations

1.	<p><u>Follow-up Observation(s)</u></p> <p>Mud trail found at the vehicle exit point at NB60 has been removed and the wheel washing area has been paved with concrete. (Closed)</p> <p><u>New Observation(s)</u></p>
2.	<p>Public access road near site boundary was observed dusty at SA310. The Contractor was advised to clean up the road and implement effective measures to prevent muddy surface runoff being spilled from the site to public area.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
	<p><u>Follow-up Observation(s) – 02/HY/2015</u></p> <p>Nil.</p> <p><u>New Observation(s) – 02/HY/2015</u></p> <p>Nil.</p> <p><u>Reminder (s) – 02/HY/2015</u></p> <p>Nil.</p>

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		6 March 2018
Checked by	Y W Fung		6 March 2018

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	15 March 2018
Time:	14:00
Inspection No.:	226

Non-compliance

Nil

Observations

1.	<p><u>Follow-up Observation(s)</u></p> <p>Dusty public access road near site boundary at SA310 has been cleaned up. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder (s)</u></p>
2.	<p>The Contractor was reminded to cover the exposed stockpile of dusty materials at SA346 entirely with impervious sheeting for dust suppression.</p>
3.	<p>The Contractor was reminded to clean up the dust on public access road at Tai Wo Service Road West regularly.</p>
4.	<p><u>Follow-up Observation(s) – 02/HY/2015</u></p> <p>Nil.</p> <p><u>New Observation(s) – 02/HY/2015</u></p> <p>Exposed stockpile of dusty materials without proper cover was observed. The Contractor was advised to cover the stockpile entirely with impervious sheeting.</p> <p><u>Reminder (s) – 02/HY/2015</u></p> <p>Nil.</p>

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		15 March 2018
Checked by	Y W Fung		15 March 2018

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	20 March 2018
Time:	14:00
Inspection No.:	227

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. The exposed stockpile of dusty materials at SA346 has been covered entirely with impervious sheeting for dust suppression. (Closed)</p> <p>2. Dust on public access road at Tai Wo Service Road West has been cleaned and a water bower has been deployed to wash the road in daily basis. (Closed)</p> <p><u>New Observation(s)</u></p> <p>3. Exposed stockpiles of dusty materials were observed at SA340. The Contractor was advised to cover the stockpiles entirely with impervious sheeting for dust suppression.</p> <p>4. Chemical containers without secondary containment were observed at SA340. The Contractor was advised to provide drip tray for the chemical containers to avoid potential leakage.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p> <p><u>Follow-up Observation(s) – 02/HY/2015</u></p> <p>5. Exposed stockpile of dusty materials without proper cover has been covered with impervious sheeting entirely. (Closed)</p> <p><u>New Observation(s) – 02/HY/2015</u></p> <p>Nil.</p> <p><u>Reminder (s) – 02/HY/2015</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		20 March 2018
Checked by	Y W Fung	/	20 March 2018

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	27 March 2018
Time:	14:00
Inspection No.:	228

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> Exposed stockpiles of dusty materials observed at SA340 have been covered entirely with impervious sheeting for dust suppression. (Closed) Chemical containers without secondary containment observed at SA340 have been removed. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> Exposed stockpiles of dusty materials were observed at SA329. The Contractor was advised to cover the stockpiles entirely with impervious sheeting for dust suppression. Mud trail and dusty materials were observed near vehicle exit points at NB60. The Contractor was advised to clear the dusty materials and pave the wheel washing area with hardcore. <p><u>Reminder (s)</u></p> <ol style="list-style-type: none"> The Contractor was reminded to plug the opening of the drip tray observed at NB60 to prevent potential leakage. <p><u>Follow-up Observation(s) – 02/HY/2015</u></p> <p>Nil.</p> <p><u>New Observation(s) – 02/HY/2015</u></p> <p>Nil.</p> <p><u>Reminder (s) – 02/HY/2015</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		27 March 2018
Checked by	Y W Fung		27 March 2018