



Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|----------------|
| Date: | 8 October 2019 |
| Time: | 14:00 |
| Inspection No.: | 308 |

| ٨ | Inr | i-co | mn | lian | 2 |
|----|------|------|----|-------|---------|
| ı١ | IUI. | トしし | шы | ııaıı | c_{c} |

Nil

O<u>bservations</u>

Follow-up Observation(s)

- 1. Water spraying was implemented at the haul road for dust suppression.
- 2. The improper stored general refuse was removed.
- 3. Water spraying was implemented during dust cleaning work carried at the construction site.

New Observation(s)


Nil

Reminder(s)

4. The Contractor was reminded to provide an entire surrounding for the construction material storage area at SA310.

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|----------------|
| Prepared by | Alex Chan | Alee | 8 October 2019 |
| Checked by | Y W Fung | / | 8 October 2019 |





Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|-----------------|
| Date: | 15 October 2019 |
| Time: | 14:00 |
| Inspection No.: | 309 |

Non-compliance

Nil

O<u>bservations</u>

Follow-up Observation(s)

1. An entire surrounding was provided to the construction material stored at SA310.

New Observation(s)

2. Stockpile placed near to river was observed at SA310. The Contractor was advised to provide a blockage on the boundary of stockpile to prevent the silt enter the river.

Reminder(s)

3. The Contractor was advised to replace the decolored NRMM label at SA346.

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|-----------------|
| Prepared by | Alex Chan | Alee | 15 October 2019 |
| Checked by | Y W Fung | / | 15 October 2019 |







BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|-----------------|
| Date: | 24 October 2019 |
| Time: | 14:00 |
| Inspection No.: | 310 |

Non-compliance

Nil

Observations

Follow-up Observation(s)

- 1. Impervious sheeting was provided to the boundary of stockpile stored at SA310 to prevent the silt of stockpile enter the river.
- 2. The decolored NRMM label was replaced by new one.

New Observation(s)


- 3. Stockpile stored without cover was observed at SA310. The Contractor was advised to cover the stockpile on site for preventing dust.
- 4. Improper storage of construction waste was observed at SA324. The Contractor was advised to sort the construction waste on site and store in a proper area.

Reminder(s)

Nil

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|-----------------|
| Prepared by | Alex Chan | Alee | 24 October 2019 |
| Checked by | Y W Fung | / | 24 October 2019 |





Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|-----------------|
| Date: | 29 October 2019 |
| Time: | 14:00 |
| Inspection No.: | 311 |

| ١ | Non-compliance | | | |
|---|----------------|--|--|--|
| | Nil | | | |

Observations

Follow-up Observation(s)

- 1. The uncovered stockpile at SA310 was removed. (Closed)
- 2. The Improper stored construction waste at SA324 was removed. (Closed)

New Observation(s)

3. The haul road at SA310 was observed dry. The Contractor was advised to implement dust control measure for dust suppression.

Reminder(s)

Nil

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|-----------------|
| Prepared by | Alex Chan | flee | 29 October 2019 |
| Checked by | Y W Fung | / | 29 October 2019 |