

Appendix M Investigation Report for Exceedances

Entrusted Portion of Widening of Tolo Highway / Fanling Highway between Island House Interchange and Fanling Stage 2

Investigation Report of Environmental Quality Exceedance(s)

Ref. No.: W161212_DO

Date	12 December 2016
Time	11:19 AM
Monitoring Location	I5 - downstream of Ma Wat River at Yuen Leng
Parameter	Dissolved Oxygen
Action / Limit Levels	Action Level: 6.7 mg/L Limit Level: 4 mg/L or 40% saturation at 15 degree Celsius
Measured Level	6.0mg/L (Action level being exceeded)
Possible reason for the exceedance	According to the Contractor's work programme, there was no construction works being carried out in the proximity of the river channel during the water sampling on 12 December 2016 (refer to the attached photos) and the exceedance would unlikely due to the construction site.
Action taken / to be taken	As the non-compliance was non-project related, no further investigation and remedial measure(s) would be required.
Remarks	-

Site photos at I5 during water sampling (Date: 12 December 2016)

