

Appendix M Investigation Report for Exceedances

Entrusted Portion of Widening of Tolo Highway / Fanling Highway between Island House Interchange and Fanling Stage 2

Investigation Report of Environmental Quality Exceedance(s)

Ref. No.: W170208_DO

Date	8 February 2017
Time	9:22 AM
Monitoring Location	I5 - downstream of Ma Wat River at Yuen Leng
Parameter	Dissolved Oxygen
Action / Limit Levels	Action Level: 6.7 mg/L Limit Level: 4 mg/L or 40% saturation at 15 degree Celsius
Measured Level	5.2mg/L (Action level being exceeded)
Possible reason for the exceedance	The exceedance has been investigated and was considered not related to the project works as DO levels were low among all monitoring stations, including the control stations. No abnormal condition was observed during the monitoring. As such, the natural variation of water quality has been considered attributed to the low DO level.
Action taken / to be taken	As the non-compliance was non-project related, no further investigation and remedial measure(s) would be required.
Remarks	-

Site photos during water sampling (Date: 8 February 2017)



(At C3a)



(At I5)