

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	1 December 2015
Time:	14:00
Inspection No.:	107

*Non-compliance*


Nil
-----

*Observations*

<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Oscar Yip		2 December 2015
Checked by	Y W Fung		2 December 2015

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	8 December 2015
Time:	14:00
Inspection No.:	108

*Non-compliance*



Nil
-----

*Observations*

<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>1. The Contractor should provide sufficient mitigation measures to prevent deposited silt and grit from entering public drainage.</li> <li>2. Chemical containers were observed placed on bare ground. The Contractor should provide drip tray to the chemicals to prevent leakage to ground.</li> </ol> <p><u>Reminder(s)</u></p> <p>Nil.</p>
---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Oscar Yip		15 December 2015
Checked by	Y W Fung		15 December 2015

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	17 December 2015
Time:	14:00
Inspection No.:	109

*Non-compliance*

Nil
-----

*Observations*

Follow-up Observation(s)

- Sand bags were provided to prevent deposited slit and grit from entering public drainage. (Closed)
- Chemical containers were put in drip tray. (Closed)

New Observation(s)



- Dry open site area was observed at precasting yard. The Contractor should dampen the road to reduce dust generation.

Reminder(s)

Refuse was observed in several locations. The Contractor should improve the housekeeping.

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Oscar Yip		21 December 2015
Checked by	Y W Fung		21 December 2015

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	23 December 2015
Time:	14:00
Inspection No.:	110

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Watering was provided to the works area at precasting yard. (Closed)</p>
	<p><u>New Observation(s)</u></p> <p>2. Proper bunding was absent at site entrance at works area SA320. The Contractor should provide bunding to avoid waste water to be carried to the public road.</p> <p>3. Idling excavators were observed at works area SA320 and SA 332 without NRMM labels. The Contractor should provide proper labels to the non-road mobile machineries.</p>
	<p><u>Reminder(s)</u></p> <p>Nil</p>

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Isabella Yeung		30 December 2015
Checked by	Y W Fung		30 December 2015

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	30 December 2015
Time:	14:00
Inspection No.:	111

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Sand bags have been laid to prevent leakage of surface runoff at works area SA320. (Closed)</li> <li>Corresponding NRMM labels were affixed to the excavators at works area SA320 and SA322. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Idling excavator was observed at works area 340. The Contractor should provide proper NRMM label to the non-road mobile machinery onsite.</li> </ol> <p><u>Reminder(s)</u></p> <p>Nil</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Isabella Yeung		4 January 2016
Checked by	Y W Fung	---	4 January 2016