

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	7 June 2016
Time:	14:00
Inspection No.:	134

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> 1. Slurry and mud trail observed at site entrance of SA329 had been cleaned up properly. (Closed) 2. Oil stains observed on ground at SA328 had been removed properly. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 3. Muddy water and mud trail was observed on public road at SA328. The contractor should clean up the muddy water and mud trail properly. 4. Mud trail was observed on public road at SA328. The contractor should clean up the mud trail properly. 5. Mud trail was observed on pedestrian access at SA325. The contractor should clean up the mud trail properly. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Adam Zhu		8 June 2016
Checked by	Y W Fung		8 June 2016

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	16 June 2016
Time:	14:00
Inspection No.:	135

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> Muddy water and mud trail observed on public road at SA328 had been cleaned up properly. (Closed) Mud trail observed on public road at SA328 had been cleaned up properly. (Closed) Mud trail observed on pedestrian access at SA325 had been cleaned up properly. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> Mud trail was observed on pedestrian road and public road at NB48. The contractor should clean up the mud trail properly and provide sufficient measures to prevent recurrence of this problem. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Adam Zhu		17 June 2016
Checked by	Y W Fung		17 June 2016

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	21 June 2016
Time:	14:00
Inspection No.:	136

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. Mud trail observed on pedestrian road and public road at NB48 had been cleaned up properly. (Closed)</p>
	<p><u>New Observation(s)</u></p> <p>2. Chemical containers without drip tray were observed onsite at SA320. The contractor should provide drip tray to the chemical containers properly.</p>
	<p><u>Reminder(s)</u></p> <p>Nil.</p>

Remarks

Nil

	Name	Signature	Date
Prepared by	Adam Zhu		23 June 2016
Checked by	Y W Fung		23 June 2016

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	28 June 2016
Time:	14:00
Inspection No.:	137

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. Chemical containers without drip tray observed onsite at SA320 had been removed properly. (Closed)</p>
	<p><u>New Observation(s)</u></p> <p>2. Muddy water and mud trail was observed on public road at Tai Wo footbridge. The contractor should clean up the muddy water and mud trail properly.</p> <p>3. Stagnant water was observed at Tai Wo footbridge. The contractor should remove the stagnant water properly.</p>
	<p><u>Reminder(s)</u></p> <p>Nil.</p>

Remarks

Nil

	Name	Signature	Date
Prepared by	Adam Zhu		29 June 2016
Checked by	Y W Fung		29 June 2016