



# **Site Inspection Summary**

Inspection Information

Contract No.	HY/2012/06	
Date:	2 May 2018	
Time:	14:00	
Inspection No.:	233	

Non-com	nliance
I VOII COIII	phanice

Nil

### Observations

## Follow-up Observation(s)

Dusty materials found near the vehicle exit points at NB60 has been cleared and one of the site entrances has been closed. (Closed)

## New Observation(s)

2. Mud trails were observed at NB60. The Contractor was advised to clear the mud trails and ensure all vehicles are properly wheel-washed before leaving the site.

4. The Contractor was reminded to wrap the breaker tip at NB60 before operation as a noise mitigation measure.

Follow-up Observation(s) - 02/HY/2015


Nil.

New Observation(s) - 02/HY/2015

Reminder (s) - 02/HY/2015

# Remarks

	Name	Signature	Date
Prepared by	Sammi Lam	Cerson	2 May 2018
Checked by	Y W Fung	0 1	2 May 2018





# **Site Inspection Summary**

Inspection Information

Contract No.	HY/2012/06
Date:	8 May 2018
Time:	09:30
Inspection No.:	234

Non-compliance

## Observations

## Follow-up Observation(s)

- Mud trails observed at NB60 have been cleared. (Closed) 1.
- 2. The breaker tip without wrapping observed at NB60 was no longer in use. (Closed)

## New Observation(s)

Mud trails were observed at W78. The Contractor was advised to clear the mud trails and ensure all 3. vehicles are properly wheel-washed before leaving the site.

## Reminder (s)

Nil.

Follow-up Observation(s) - 02/HY/2015

Nil.

New Observation(s) - 02/HY/2015

Nil.

Reminder (s) - 02/HY/2015

Nil.

# Remarks

	Name	Signature	Date
Prepared by	Sammi Lam	Costr	8 May 2018
Checked by	Y W Fung	0 1	8 May 2018



WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

# **Site Inspection Summary**

Inspection Information

Contract No.	HY/2012/06
Date:	17 May 2018
Time:	14:00
Inspection No.:	235

N	on-	com	plia	nce

Nil

## Observations

Follow-up Observation(s)

1. Mud trails observed at W78 have been cleared. (Closed)

New Observation(s)

3. The Contractor was reminded to ensure all vehicles are properly wheel-washed before leaving the site at SA340.

Reminder (s)

Nil.

Follow-up Observation(s) - 02/HY/2015

Nil.

New Observation(s) - 02/HY/2015

Nil.

Reminder (s) - 02/HY/2015

Nil.

## Remarks

	Name	Signature	Date
Prepared by	Sammi Lam	(www	17 May 2018
Checked by	Y W Fung	0 1	17 May 2018

EM&A Environmental Inspection Record WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

## **Site Inspection Summary**

Inspection Information

Contract No.	HY/2012/06
Date:	25 May 2018
Time:	09:30
Inspection No.:	236

Non-compliance

Nil

# Observations

# Follow-up Observation(s)

Vehicles are properly wheel-washed before leaving the site at SA340 to maintain the site entrance clean. (Closed)

# New Observation(s)

2. The Contractor was reminded to maintain the vehicular exit free from dusty material at Tai Wo Service Road West.

### Reminder (s)

Nil.

Follow-up Observation(s) - 02/HY/2015

New Observation(s) - 02/HY/2015

Nil.

Reminder (s) - 02/HY/2015

Nil.

## Remarks

	Name	Signature	Date
Prepared by	Ray Chow	(arlup.p.	25 May 2018
Checked by	Y W Fung		25 May 2018



WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

# **Site Inspection Summary**

Inspection Information

Contract No.	HY/2012/06
Date:	29 May 2018
Time:	14:00
Inspection No.:	237

Non-compliance

Nil

# Observations

Follow-up Observation(s)

The vehicular exit at Tai Wo Service Road West has been closed and cleaned. (Closed)

New Observation(s)

2. Some chemical containers were observed without drip trays at SA340. The Contractor was advised to provide chemical containers with secondary containment.

Reminder (s)

Nil.

Follow-up Observation(s) - 02/HY/2015

Nil.

New Observation(s) - 02/HY/2015

Nil.

Reminder (s) - 02/HY/2015

Nil.

## Remarks

	Name	Signature	Date
Prepared by	Ray Chow	Surtup.p.	29 May 2018
Checked by	Y W Fung		29 May 2018