

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	8 January 2019
Time:	14:00
Inspection No.:	269

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Chemical container without secondary containment observed at NB48 has been provided with drip tray to prevent potential leakage. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Exposed stockpile of dusty materials without proper cover was observed at W78. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression.</p> <p>3. Chemical container without secondary containment was observed at W78. The Contractor was advised to provide drip tray for the chemical container to prevent potential leakage.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		8 January 2019
Checked by	Y W Fung	/	8 January 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	17 January 2019
Time:	14:00
Inspection No.:	270

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Exposed stockpile of dusty materials without proper cover observed at W78 has been removed. (Closed)</li> <li>Chemical container without secondary containment observed at W78 has been removed. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Dry exposed area without sufficient water spraying was observed at NB50A. The Contractor was advised to spray the dry exposed area with water regularly for dust suppression.</li> <li>Excessive accumulation of general refuse was found at SA328. The Contractor was advised to dispose of the general refuse off site regularly to keep the site clean and tidy.</li> <li>Chemical container without secondary containment was observed at NB50A. The Contractor was advised to provide drip tray for the chemical container to prevent potential leakage.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		17 January 2019
Checked by	Y W Fung	/	17 January 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	24 January 2019
Time:	14:00
Inspection No.:	271

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>1. Dry exposed area without sufficient water spraying observed at NB50A has been sprayed with water for dust suppression. (Closed)</li> <li>2. Excessive accumulation of general refuse found at SA328 has been removed to keep the site clean and tidy. (Closed)</li> <li>3. Chemical container without secondary containment observed at NB50A has been removed. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder (s)</u></p> <ol style="list-style-type: none"> <li>4. The Contractor was reminded to spray the dry exposed area with water regularly at NB60 for dust suppression.</li> </ol>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		24 January 2019
Checked by	Y W Fung	/	24 January 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	29 January 2019
Time:	14:00
Inspection No.:	272

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Water has been sprayed for the dry exposed area at NB60 for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Mud trails were observed near the site entrance at NN54. The Contractor was advised to clear the dusty materials at the site entrance and ensure all vehicle are properly wheel-washed before leaving the site.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		29 January 2019
Checked by	Y W Fung	/	29 January 2019