

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	4 February 2019
Time:	09:30
Inspection No.:	273

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. Mud trails observed near the site entrance at NN54 have been removed. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		4 February 2019
Checked by	Y W Fung	/	4 February 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	12 February 2019
Time:	14:00
Inspection No.:	274

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 1. Dusty materials were observed on public road near the site boundary at NB50. The Contractor was advised to remove the dusty materials and ensure proper protection is provided along the site boundary to prevent leakage of surface runoff. 2. Excessive accumulation of construction wastes and general refuse were found at NB48. The Contractor was advised to segregate general refuse from construction wastes and dispose of separately. <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		12 February 2019
Checked by	Y W Fung	/	12 February 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	21 February 2019
Time:	14:00
Inspection No.:	275

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> Dusty materials observed on public road near the site boundary at NB50 has been removed. Excessive accumulation of construction wastes and general refuse found at NB48 has been covered for temporary storage. <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		21 February 2019
Checked by	Y W Fung	/	21 February 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	28 February 2019
Time:	14:00
Inspection No.:	276

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> Inadequate watering for dry exposed area was found at W78. The Contractor was advised to spray the exposed area with water regularly for dust suppression. Improper cover for exposed stockpile of more than 20 bags of cement was found at SA340. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression. <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		28 February 2019
Checked by	Y W Fung	/	28 February 2019