

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	5 March 2019
Time:	14:00
Inspection No.:	277

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>Dry exposed area without adequate found at W78 has been sprayed with water for dust suppression. (Closed)</li> <li>Exposed stockpile of more than 20 bags of cement found at SA340 have been covered entirely with impervious sheeting for dust suppression. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>Chemical containers without secondary containment were found at NB48. The Contractor was advised to provide drip tray for the chemical containers to prevent potential leakage or dispose of the contaminated containers as chemical wastes.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		5 March 2019
Checked by	Y W Fung	/	5 March 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	12 March 2019
Time:	14:00
Inspection No.:	278

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Chemical containers without secondary containment found at NB48 have been removed off-site. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Exposed stockpile of dusty materials without proper cover was found at NB62. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		12 March 2019
Checked by	Y W Fung	/	12 March 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	21 March 2019
Time:	14:00
Inspection No.:	279

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Exposed stockpile of dusty materials without proper cover found at NB62 has been covered entirely with impervious sheeting for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan	Alex Chan	21 March 2019
Checked by	Y W Fung	/	21 March 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	28 March 2019
Time:	14:00
Inspection No.:	280

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>1. Exposed stockpile of dusty materials without proper cover was observed at Tai Wo Bridge. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression.</li> <li>2. Muddy water outside the site boundary was observed at Tai Wo Bridge. The Contractor was advised to clear the muddy water and ensure sufficient measures are implemented to prevent surface runoff spilling out of the site area.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		28 March 2019
Checked by	Y W Fung	/	28 March 2019