

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	2 April 2019
Time:	14:00
Inspection No.:	281

Non-compliance


Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	Exposed stockpile of dusty materials without proper cover observed at Tai Wo Bridge has been removed. (Closed)
2.	Muddy water outside the site boundary observed at Tai Wo Bridge has been cleared. (Closed)
	<u>New Observation(s)</u>
3.	Exposed stockpiles of dusty materials without proper cover were observed at Tai Hang Bridge and W78. The Contractor was advised to cover the stockpiles entirely with impervious sheeting for dust suppression.
	<u>Reminder (s)</u>
	Nil.

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		2 April 2019
Checked by	Y W Fung	/	2 April 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	9 April 2019
Time:	14:00
Inspection No.:	282

Non-compliance


Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	Exposed stockpiles of dusty materials without proper cover observed at Tai Hang Bridge has been covered entirely with impervious sheeting for dust suppression and that observed at W78 has been removed. (Closed)
	<u>New Observation(s)</u>
2.	Excessive construction waste and general refuse were observed at SA328. The Contractor was advised to segregate construction waste and general refuse prior to disposing of regularly.
	<u>Reminder (s)</u>
	Nil.

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		9 April 2019
Checked by	Y W Fung	/	9 April 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	18 April 2019
Time:	14:00
Inspection No.:	283

Non-compliance


Nil

Observations

1.	<u>Follow-up Observation(s)</u>
	Excessive construction waste and general refuse observed at SA328 have been removed. (Closed)
	<u>New Observation(s)</u>
	Nil.
2.	<u>Reminder (s)</u>
	The Contractor was reminded to remove the stagnant water observed at SA329 or apply larvicidal oil to prevent mosquito breeding.

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		18 April 2019
Checked by	Y W Fung	/	18 April 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	23 April 2019
Time:	14:00
Inspection No.:	284

Non-compliance


Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	The stagnant water observed at SA329 has been removed. (Closed)
	<u>New Observation(s)</u>
2.	Retained water in drip trays of chemical container and generator was observed at NB54. The Contractor was advised to clean up the drip trays to prevent overflow and potential leakage.
	<u>Reminder (s)</u>
	Nil.

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		23 April 2019
Checked by	Y W Fung	/	23 April 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	30 April 2019
Time:	14:00
Inspection No.:	285

Non-compliance


Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	Retained water in drip trays of chemical container and generator observed at NB54 has been cleaned up to prevent overflow and potential leakage. (Closed)
	<u>New Observation(s)</u>
2.	Chemical containers without secondary containment were observed at W76 and near Wo Hop Shek Bridge. The Contractor was advised to provide drip trays to the chemical containers to prevent potential leakage.
	<u>Reminder (s)</u>
	Nil.

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		30 April 2019
Checked by	Y W Fung	/	30 April 2019