

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	7 May 2019
Time:	14:00
Inspection No.:	286

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Chemical containers without secondary containment observed at W76 and near Wo Hop Shek Bridge have been removed. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Colour-faded NRMM labels were observed at Tai Wo Bridge. The Contractor was advised to affix valid label for all NRMM before operation.</p> <p>3. Chemical container without secondary containment was observed at Tai Wo Bridge. The Contractor was advised to provide drip tray for the chemical container to prevent potential leakage.</p> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		7 May 2019
Checked by	Y W Fung	/	7 May 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	14 May 2019
Time:	14:00
Inspection No.:	287

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>1. Colour-faded NRMM labels observed at Tai Wo Bridge has been replaced with valid labels. (Closed)</li> <li>2. Chemical container without secondary containment observed at Tai Wo Bridge has been removed. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>3. Excessive accumulation of construction waste was observed at SA346. The Contractor was advised to segregate the construction waste and dispose of regularly.</li> </ol> <p><u>Reminder (s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		14 May 2019
Checked by	Y W Fung	/	14 May 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	23 May 2019
Time:	14:00
Inspection No.:	288

*Non-compliance*


Nil
-----

*Observations*

	<u>Follow-up Observation(s)</u>
1.	Excessive accumulation of construction waste observed at SA346 has been removed. (Closed)
	<u>New Observation(s)</u>
2.	Exposed stockpiles of dusty materials without proper cover were observed at SA346. The Contractor was advised to cover the stockpiles entirely with impervious sheeting for dust suppression.
	<u>Reminder (s)</u>
	Nil.

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		23 May 2019
Checked by	Y W Fung	/	23 May 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	30 May 2019
Time:	14:00
Inspection No.:	289

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Exposed stockpiles of dusty materials without proper cover observed at SA346 have been covered entirely with impervious sheeting for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Chemical containers without secondary containment were observed at NB42A. The Contractor was advised to provide drip trays for the chemical containers to prevent potential leakage.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		30 May 2019
Checked by	Y W Fung	/	30 May 2019