

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	2 July 2019
Time:	14:00
Inspection No.:	294

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> Exposed stockpile of dusty materials without proper cover was observed at NB50. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression. Excessive accumulation of construction wastes and general refuse were found at NB48. The Contractor was advised to segregate the construction wastes and general refuse and dispose of regularly. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		2 July 2019
Checked by	Y W Fung	/	2 July 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	9 July 2019
Time:	14:00
Inspection No.:	295

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. Exposed stockpile of dusty materials without proper cover observed at NB50 has been removed. (Closed)</p> <p>2. Excessive accumulation of construction wastes and general refuse found at NB48 has been removed. (Closed)</p> <p><u>New Observation(s)</u></p> <p>3. Exposed stockpiles of dusty materials without proper cover were observed at SA340. The Contractor was advised to cover the stockpiles entirely with impervious sheeting for dust suppression.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		9 July 2019
Checked by	Y W Fung	/	9 July 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	18 July 2019
Time:	14:00
Inspection No.:	296

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. Exposed stockpiles of dusty materials without proper cover observed at SA340 have been removed or covered entirely with impervious sheeting for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		18 July 2019
Checked by	Y W Fung	/	18 July 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	23 July 2019
Time:	14:00
Inspection No.:	297

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>Nil.</p> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 1. A stockpile of more than 20 bags of cement without proper cover was observed at Tai Wo Bridge. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression. 2. Chemical containers without secondary containment were observed at Tai Wo Bridge. The Contractor was advised to provide drip tray for the chemical containers to prevent potential leakage. <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		23 July 2019
Checked by	Y W Fung	/	23 July 2019

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	30 July 2019
Time:	14:00
Inspection No.:	298

Non-compliance

Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> 1. A stockpile of more than 20 bags of cement without proper cover observed at Tai Wo Bridge has been covered entirely with impervious sheeting for dust suppression.(Closed) 2. Chemical containers without secondary containment observed at Tai Wo Bridge have been removed. (Closed) <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> 3. A stockpile of more than 20 bags of cement without proper cover was observed at SA340. The Contractor was advised to cover the stockpile entirely with impervious sheeting for dust suppression. 4. Exposed stockpiles of dusty materials without proper cover were observed at Wo Hop Shek Bridge. The Contractor was advised to cover the exposed stockpiles entirely with impervious sheeting for dust suppression. <p><u>Reminder(s)</u></p> <ol style="list-style-type: none"> 5. The Contractor was reminded to provide bunding at W78 to intercept surface runoff from the exposed earth to prevent leaking out of the site boundary.
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Sammi Lam		30 July 2019
Checked by	Y W Fung	/	30 July 2019