

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	6 August 2019
Time:	14:00
Inspection No.:	299

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> <li>1. A stockpile of more than 20 bags of cement without proper cover observed at SA340 has been covered entirely with impervious sheeting for dust suppression. (Closed)</li> <li>2. Exposed stockpiles of dusty materials without proper cover observed at Wo Hop Shek Bridge were covered entirely with impervious sheeting for dust suppression. (Closed)</li> <li>3. Road surface at W78 has been elevated to prevent surface runoff from the exposed earth to prevent leaking out of the site boundary. (Closed)</li> </ol> <p><u>New Observation(s)</u></p> <ol style="list-style-type: none"> <li>4. Chemical container without secondary containment were observed at NB61. The Contractor was advised to provide drip tray for the containers to prevent potential leakage.</li> </ol> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		6 August 2019
Checked by	Y W Fung	/	6 August 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	13 August 2019
Time:	14:00
Inspection No.:	300

*Non-compliance*

Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Chemical container without secondary containment observed at NB61 has been removed. (Closed)</p> <p><u>New Observation(s)</u></p> <p>2. Exposed stockpiles of dusty materials without proper cover were observed at SA340. The Contractor was advised to cover the exposed stockpiles entirely with impervious sheeting for dust suppression.</p> <p><u>Reminder(s)</u></p> <p>Nil.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		13 August 2019
Checked by	Y W Fung	/	13 August 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	22 August 2019
Time:	14:00
Inspection No.:	301

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. Exposed stockpiles of dusty materials without proper cover observed at SA340 have been covered entirely with impervious sheeting for dust suppression. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder(s)</u></p> <p>2. The Contractor was reminded to remove the construction waste in the site regularly for maintaining site tidiness.</p>
--	---

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		22 August 2019
Checked by	Y W Fung	/	22 August 2019

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	27 August 2019
Time:	14:00
Inspection No.:	302

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. The construction waste at the site has been removed for maintaining site tidiness. (Closed)</p> <p><u>New Observation(s)</u></p> <p>Nil.</p> <p><u>Reminder(s)</u></p> <p>2. The Contractor was reminded to dispose of the construction waste at SA340 regularly for maintaining site tidiness.</p>
--	--

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Sammi Lam		27 August 2019
Checked by	Y W Fung	/	27 August 2019