

Inspection Information

Contract No.	HY/2012/06
Date:	3 December 2019
Time:	14:00
Inspection No.:	315

Non-compliance

Nil

Observations

	Follow-up Observation(s)
1.	The stockpile at SA340 was covered with imperious sheeting. (closed)
	New Observation(s)
2.	Stockpile placed at the site without cover was observed at SA340. The Contractor was advised to cover or remove the stockpile at SA340.
	Reminder(s)
	Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	3 December 2019
Checked by	Y W Fung	/	3 December 2019



Inspection Information

Contract No.	HY/2012/06
Date:	10 December 2019
Time:	14:00
Inspection No.:	316

Non-compliance

Nil

Observations

	Follow-up Observation(s)
1.	The stockpile at SA340 was covered with imperious sheeting. (closed)
	New Observation(s)
	Nil
	Reminder(s)
2.	The Contractor was reminded to improve the housekeeping at SA310.

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	10 December 2019
Checked by	Y W Fung	/	10 December 2019



Inspection Information

Contract No.	HY/2012/06
Date:	20 December 2019
Time:	14:00
Inspection No.:	317

Non-compliance

Nil

Observations

	Follow-up Observation(s)		
1.	The refuse at the SA310 was remove. (closed)		
	New Observation(s)		
	Nil		
	Reminder(s)		
	Nil		

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	20 December 2019
Checked by	Y W Fung	/	20 December 2019



Inspection Information

Contract No.	HY/2012/06
Date:	24 December 2019
Time:	14:00
Inspection No.:	318

Non-compliance

Nil

Observations

	Follow-up Observation(s)
	Nil
	New Observation(s)
1.	General refuse placed at SA310 was observed. The Contractor was advised to remove the general refuse and improve the site tidiness.
	Reminder(s)
	Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	24 December 2019
Checked by	Y W Fung	/	24 December 2019



Inspection Information

Contract No.	HY/2012/06
Date:	31 December 2019
Time:	14:00
Inspection No.:	319

Non-compliance

Nil

Observations

	Follow-up Observation(s)
1.	The general refuse at SA310 was removed. (closed)
	New Observation(s)
2.	Improper storage of construction waste was observed at SA324. The Contractor was advised to remove the construction waste regularly.
	Reminder(s)
	Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	31 December 2019
Checked by	Y W Fung	/	31 December 2019