

Inspection Information

Contract No.	HY/2012/06
Date:	3 March 2020
Time:	14:00
Inspection No.:	327

Non-compliance

Nil

Observations

	Follow-up Observation(s)
1.	The bulldozer affixed damaged NRMM at SA310 was removed. (closed)
	New Observation(s)
2.	Stockpile placed without cover was observed at SA310. The Contractor was advised to cover the stockpile with imperious sheeting.
	Reminder(s)
	Nil
Rem	arks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	3 March 2020
Checked by	Y W Fung	/	3 March 2020



Inspection Information

Contract No.	HY/2012/06
Date:	10 March 2020
Time:	14:00
Inspection No.:	328

Non-compliance

Nil

Observations

Follow-up Observation(s)

1. The stockpile at SA310 was removed. (closed)

New Observation(s)

2. Large amount of exposed stockpile was observed at SA340. The Contractor was advised to implement dust control measure for dust suppression.

Reminder(s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	flee	10 March 2020
Checked by	Y W Fung	/	10 March 2020



Inspection Information

Contract No.	HY/2012/06
Date:	17 March 2020
Time:	14:00
Inspection No.:	329

Non-compliance

Nil

Observations

Follow-up Observation(s)

1. The stockpile at SA340 was backfilled. (closed)

New Observation(s)

2. Nil

Reminder(s)

The Contractor was reminded to cover the stockpile at SA340 with imperious sheeting.

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	17 March 2020
Checked by	Y W Fung	/	17 March 2020







Inspection Information

Contract No.	HY/2012/06
Date:	24 March 2020
Time:	14:00
Inspection No.:	330

Non-compliance

Nil

Observations

	Follow-up Observation(s)
1.	Imperious sheeting was provided to stockpile at SA340. (closed)
	New Observation(s)
2.	Nil
	Reminder(s)
	Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	flee	24 March 2020
Checked by	Y W Fung	/	24 March 2020



Inspection Information

Contract No.	HY/2012/06
Date:	31 March 2020
Time:	14:00
Inspection No.:	331

Non-compliance

Nil

Observations

Nil

New Observation(s)

1. Silt was observed outside boundary of SA340. The Contractor was advised to remove the silt.

Reminder(s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	flee	31 March 2020
Checked by	Y W Fung	/	31 March 2020