



Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	7 July 2020
Time:	14:00
Inspection No.:	345

Non-comp	pliance	
Nil		
Observation	ions	

Follow-up Observation(s)

The chemical waste container at SA340 was removed. (closed) 1.

New Observation (s)

Nil


Reminder(s)

Nil

\Box	$\overline{}$	m	_	rl	kc

	Name	Signature	Date
Prepared by	Alex Chan	Alee	7 July 2020
Checked by	Y W Fung	/	7 July 2020

EM&A Environmental Inspection Record





Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06		
Date:	14 July 2020		
Time:	14:00		
Inspection No.:	345		

Non-compliance

Nil

Observations

Follow-up Observation(s)

Nil

New Observation (s)


- 1. Silt was observed at the site entrance of SA340. The Contractor was advised to wash the wheel before vehicle leaving the construction site.
- 2. Stockpile stored without cover was observed at SA340. The Contractor was advised to cover the stockpile with imperious sheeting.

Reminder(s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	flee	14 July 2020
Checked by	Y W Fung	/	14 July 2020





EM&A Environmental Inspection Record WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	21 July 2020
Time:	14:00
Inspection No.:	346

Λ	Non-compliance			
	Nil			

Observations

1.

I	
I	The silt at the site entrance of SA340 was removed. (closed)

2. The stockpile at SA340 was removed. (closed)

New Observation (s)

Follow-up Observation(s)

Nil

Reminder(s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	21 July 2020
Checked by	Y W Fung	/	21 July 2020

EM&A Environmental Inspection Record





WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	28 July 2020
Time:	14:00
Inspection No.:	347

Nor	-com	pliand	e
I VOI	1-60111	piiaiio	⊂

Nil

Observations

Follow-up Observation(s)

Nil

New Observation (s)

Breaking work carried without dust control measure was observed at SA342. The Contractor advised 1. to provide water spraying to the breaking work carried on site.

Reminder(s)

2. The Contractor was reminded to provide soundproof cloth to the breaker at SA324.

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	28 July 2020
Checked by	Y W Fung	/	28 July 2020