

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	4 August 2020
Time:	14:00
Inspection No.:	348

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <ol style="list-style-type: none"> The breaking work at SA324 was completed. (closed) The breaker at SA324 was removed. (closed) <p><u>New Observation (s)</u></p> <ol style="list-style-type: none"> Stockpile placed without cover was observed at SA324. The Contractor was advised to cover the stockpile with imperious sheeting. Breaking work carried without dust control measure was observed at SA340. The Contractor was advised to provide watering to the dusty work.
--	---

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		4 August 2020
Checked by	Y W Fung	/	4 August 2020

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	11 August 2020
Time:	14:00
Inspection No.:	349

Non-compliance

Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	Water spraying was provided to the stockpile at SA340. (closed)
2.	The breaking work at SA340 was completed. (closed)
	<u>Reminder (s)</u>
3.	The Contractor was reminded to clean the silt at outside boundary of SA340.

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		11 August 2020
Checked by	Y W Fung	/	11 August 2020

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	18 August 2020
Time:	14:00
Inspection No.:	350

Non-compliance

Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	The silt at outside boundary of SA340 was removed. (closed)
	<u>Observation (s)</u>
2.	Stockpile stored without cover was observed at SA340. The Contractor was advised to provide imperious sheeting to the stockpile stored on site.

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		18 August 2020
Checked by	Y W Fung	/	18 August 2020

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	25 August 2020
Time:	14:00
Inspection No.:	351

Non-compliance


Nil

Observations

	<p><u>Follow-up Observation(s)</u></p> <p>1. Imperious sheeting was provided to the stockpile at SA340. (closed)</p> <p><u>Observation (s)</u></p> <p>2. Improper disposal of general refuse and construction waste was observed at SA340. The Contractor was advised to provide sufficient waste collection point and store it properly. The Contractor was also advised to provide onsite waste sorting for the general refuse, construction waste and recyclable material.</p> <p>3. Stockpile stored without cover was observed at SA340. The Contractor was advised to provide imperious sheeting to the stockpile stored on site for dust suppression.</p> <p><u>Reminder (s)</u></p> <p>4. The Contractor was reminded to provide water spraying at exposed area of SA340 regularly.</p> <p>5. The Contractor was reminded to affix the NRMM label on the bulldozer at SA340.</p>
--	--

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		25 August 2020
Checked by	Y W Fung	/	25 August 2020