

Project Name:

**Contract No. CV/2012/09 Liantang / Heung Yuen Wai Boundary Control Point Site Formation and Infrastructure works - Contract 3**  
**Entrusted Portion of Widening of Tolo Highway / Fanling Highway between Island House Interchange and Fanling - Stage 2**

Noise Monitoring Result at SR77

Date	Weather Condition	Start Time	End Time	Measured Noise Level (dB(A))			Baseline Corrected Level, dB(A)	Baseline Noise Level (dB(A)), Leq(30min)	Limit Level dB(A)	Exceedance (Y / N)
				L10(30min)	L90(30min)	Leq(30min)				
2013/11/05	Cloudy	9:30	10:00	72.4	61.1	69.1	-	67.8	75.0	N
2013/11/11	Cloudy	10:30	11:00	72.9	62.2	71.3	-	67.8	75.0	N
2013/11/16	Fine	10:00	10:30	73.2	63.1	71.1	-	67.8	75.0	N
2013/11/22	Fine	13:30	14:00	70.5	58.5	67.6	-	67.8	75.0	N
2013/11/28	Fine	10:30	11:00	74.1	77.5	71.5	-	67.8	75.0	N
				<b>Average</b>	70.1					
				<b>Minimum</b>	67.6					
				<b>Maximum</b>	71.5					

### Noise monitoring result: SR77

