

Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|-----------------|
| Date: | 5 November 2019 |
| Time: | 14:00 |
| Inspection No.: | 312 |

Non-compliance

Nil

Observations

Follow-up Observation(s)

1. Water spray was implemented at SA310. (Closed)

New Observation(s)

2. The Open stockpile was observed at SA346. The Contractor was advised to cover the stockpile on site with imperious sheeting.

Reminder(s)

Nil

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|-----------------|
| Prepared by | Alex Chan | flee | 5 November 2019 |
| Checked by | Y W Fung | / | 5 November 2019 |



Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|------------------|
| Date: | 12 November 2019 |
| Time: | 14:00 |
| Inspection No.: | 313 |

Non-compliance

Nil

Observations

Follow-up Observation(s)

1. The stockpile at SA346 was removed. (Closed)

New Observation(s)

2. Nil.

Reminder(s)

Nil

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|------------------|
| Prepared by | Alex Chan | Alee | 12 November 2019 |
| Checked by | Y W Fung | / | 12 November 2019 |



Inspection Information

| Contract No. | HY/2012/06 | |
|-----------------|------------------|--|
| Date: | 21 November 2019 | |
| Time: | 14:00 | |
| Inspection No.: | 314 | |

Non-compliance

Nil

Observations

| Follow-up Observation(s) |
|--------------------------|
| |

Nil.

New Observation(s)

- 1. Decolored NRMM label was observed at SA310. The Contractor was advised to replace the decolored NRMM label.
- 2. The construction material and waste placed at SA346 was observed. The Contractor was advised to remove the construction material and waste, the Contractor was also advised to store the waste and material at proper area.

Reminder(s)

Nil

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|------------------|
| Prepared by | Alex Chan | flee | 21 November 2019 |
| Checked by | Y W Fung | / | 21 November 2019 |





Site Inspection Summary

Inspection Information

| Contract No. | HY/2012/06 |
|-----------------|------------------|
| Date: | 26 November 2019 |
| Time: | 14:00 |
| Inspection No.: | 315 |

Non-compliance

Nil

Observations

| | Follow-up Observation(s) |
|----|--|
| 1. | The decolored NRMM label was replaced by the new label. (closed) |
| 2. | The construction material and waste at SA346 was removed. (closed) |
| | |
| | New Observation(s) |
| 3. | Stockpile placed at the site without cover was observed at SA340. The Contractor was advised to cover the stockpile with imperious sheeting. |
| | |
| | Reminder(s) |
| | Nil |
| | |

Remarks

| | Name | Signature | Date |
|-------------|-----------|-----------|------------------|
| Prepared by | Alex Chan | Alee | 26 November 2019 |
| Checked by | Y W Fung | / | 26 November 2019 |