

### Site Inspection Summary

#### Inspection Information

Contract No.	HY/2012/06
Date:	07 January 2020
Time:	14:00
Inspection No.:	320

#### Non-compliance

Nil
-----

#### Observations

	<u>Follow-up Observation(s)</u>
1.	The improper stored construction waste at SA324 was removed. (closed)
	<u>New Observation(s)</u>
	Nil
	<u>Reminder(s)</u>
2.	The Contractor was reminded to cover the stockpile at SA340 entirely.

#### Remarks

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		07 January 2020
Checked by	Y W Fung	/	07 January 2020

## Site Inspection Summary

### Inspection Information

Contract No.	HY/2012/06
Date:	16 January 2020
Time:	14:00
Inspection No.:	321

### Non-compliance


Nil
-----

### Observations

	<u>Follow-up Observation(s)</u>
1.	The stockpile at SA340 was entirely covered. (closed)
	<u>New Observation(s)</u>
2.	Chemical waste stored without drip tray was observed at SA324. The Contractor was advised to provide the drip tray to chemical waste on site for preventing potential leakage.
	<u>Reminder(s)</u>
	Nil.

### Remarks

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		16 January 2020
Checked by	Y W Fung	/	16 January 2020

### Site Inspection Summary

#### Inspection Information

Contract No.	HY/2012/06
Date:	21 January 2020
Time:	14:00
Inspection No.:	322

#### Non-compliance


Nil
-----

#### Observations

	<u>Follow-up Observation(s)</u>
1.	The chemical waste at SA324 was removed. (closed)
	<u>New Observation(s)</u>
	Nil
	<u>Reminder(s)</u>
2.	The Contractor was reminded to cover the stockpile at SA310 with imperious sheeting.

#### Remarks

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		21 January 2020
Checked by	Y W Fung	/	21 January 2020