

### Site Inspection Summary

#### Inspection Information

Contract No.	HY/2012/06
Date:	7 February 2020
Time:	14:00
Inspection No.:	323

#### Non-compliance

Nil
-----

#### Observations

	<u>Follow-up Observation(s)</u>
1.	Imperious sheeting was provided to the stockpiles at SA310. (closed)
	<u>New Observation(s)</u>
2.	Chemical waste placed without drip tray was observed at SA340. The Contractor was advised to provide drip tray to the chemical waste on site for preventing land contamination.
	<u>Reminder(s)</u>
	Nil

#### Remarks

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		7 February 2020
Checked by	Y W Fung	/	7 February 2020

## Site Inspection Summary

### Inspection Information

Contract No.	HY/2012/06
Date:	11 February 2020
Time:	14:00
Inspection No.:	324

### Non-compliance


Nil
-----

### Observations

	<u>Follow-up Observation(s)</u>
1.	The Chemical waste at SA340 was removed. (closed)
	<u>New Observation(s)</u>
2.	Stockpiles placed without cover was observed at SA340. The Contractor was advised to cover the stockpiles on site with imperious sheeting.
	<u>Reminder(s)</u>
	Nil

### Remarks

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		11 February 2020
Checked by	Y W Fung	/	11 February 2020

**Site Inspection Summary**

*Inspection Information*

Contract No.	HY/2012/06
Date:	18 February 2020
Time:	14:00
Inspection No.:	325

*Non-compliance*


Nil
-----

*Observations*

	<p><u>Follow-up Observation(s)</u></p> <p>1. The stockpile at SA340 was covered with imperious sheeting. (closed)</p>
	<p><u>New Observation(s)</u></p> <p>2. Chemical waste containers placed at paved ground was observed at SA324. The Contractor was advised to store the chemical waste containers in drip tray.</p>
	<p><u>Reminder(s)</u></p> <p>Nil</p>

*Remarks*

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		18 February 2020
Checked by	Y W Fung	/	18 February 2020

### Site Inspection Summary

#### Inspection Information

Contract No.	HY/2012/06
Date:	25 February 2020
Time:	14:00
Inspection No.:	326

#### Non-compliance

Nil
-----

#### Observations

	<u>Follow-up Observation(s)</u>
1.	The chemical waste containers at SA324 was removed. (closed)
	<u>New Observation(s)</u>
2.	Damaged NRMM label was observed at SA310. The Contractor was advised to replace the damage NRMM.
	<u>Reminder(s)</u>
	Nil

#### Remarks

Nil
-----

	Name	Signature	Date
Prepared by	Alex Chan		25 February 2020
Checked by	Y W Fung	/	25 February 2020