

Site Inspection Summary

Inspection Information

| | |
|-----------------|------------|
| Contract No. | HY/2012/06 |
| Date: | 5 May 2020 |
| Time: | 14:00 |
| Inspection No.: | 336 |

Non-compliance

| |
|-----|
| Nil |
|-----|

Observations

| | |
|--|---|
| | <p><u>Follow-up Observation(s)</u></p> <p>1. The excavation work at SA340 was completed. (Closed)</p> |
| | <p><u>New Observation(s)</u></p> <p>2. Stockpile stored without cover was observed at SA340. The Contractor was advised to cover the stockpile with imperious sheeting.</p> <p>3. Exposed area at SA340 was observed dry. The Contractor was advised watering the exposed area regularly.</p> |
| | <p><u>Reminder(s)</u></p> <p>Nil</p> |

Remarks

| |
|-----|
| Nil |
|-----|

| | Name | Signature | Date |
|-------------|-----------|-----------|------------|
| Prepared by | Alex Chan | | 5 May 2020 |
| Checked by | Y W Fung | / | 5 May 2020 |

Site Inspection Summary

Inspection Information

| | |
|-----------------|-------------|
| Contract No. | HY/2012/06 |
| Date: | 12 May 2020 |
| Time: | 14:00 |
| Inspection No.: | 337 |

Non-compliance

| |
|-----|
| Nil |
|-----|

Observations

| | |
|----|---|
| | <u>Follow-up Observation(s)</u> |
| 1. | The stockpile at SA340 was removed. (Closed) |
| 2. | The exposed area of SA340 was kept in we for dust suppression. (Closed) |
| | <u>New Observation (s)</u> |
| 3. | Improper disposal of general refuse was observed at SA340. The Contractor was advised to provide sufficient waste collection point. |
| | <u>Reminder(s)</u> |
| | Nil |

Remarks

| |
|-----|
| Nil |
|-----|

| | Name | Signature | Date |
|-------------|-----------|--|-------------|
| Prepared by | Alex Chan |  | 12 May 2020 |
| Checked by | Y W Fung | / | 12 May 2020 |

Site Inspection Summary

Inspection Information

| | |
|-----------------|-------------|
| Contract No. | HY/2012/06 |
| Date: | 19 May 2020 |
| Time: | 14:00 |
| Inspection No.: | 338 |

Non-compliance


| |
|-----|
| Nil |
|-----|

Observations

| | |
|----|--|
| | <u>Follow-up Observation(s)</u> |
| 1. | The improper disposed waste was removed. (Closed) |
| | <u>New Observation (s)</u> |
| | Nil |
| | <u>Reminder(s)</u> |
| 2. | The Contractor was reminded to provide the drip tray to the chemical waste at SA340. |

Remarks

| |
|-----|
| Nil |
|-----|

| | Name | Signature | Date |
|-------------|-----------|--|-------------|
| Prepared by | Alex Chan |  | 19 May 2020 |
| Checked by | Y W Fung | / | 19 May 2020 |

Site Inspection Summary

Inspection Information

| | |
|-----------------|-------------|
| Contract No. | HY/2012/06 |
| Date: | 26 May 2020 |
| Time: | 14:00 |
| Inspection No.: | 339 |

Non-compliance


| |
|-----|
| Nil |
|-----|

Observations

| | |
|----|---|
| | <u>Follow-up Observation(s)</u> |
| 1. | The improper stored chemical waste at SA340 was removed. (Closed) |
| | <u>New Observation (s)</u> |
| | Nil |
| | <u>Reminder(s)</u> |
| | Nil |

Remarks

| |
|-----|
| Nil |
|-----|

| | Name | Signature | Date |
|-------------|-----------|--|-------------|
| Prepared by | Alex Chan |  | 26 May 2020 |
| Checked by | Y W Fung | / | 26 May 2020 |