



EM&A Environmental Inspection Record WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	2 June 2020
Time:	14:00
Inspection No.:	340

٨	lon-c	ompliance
		Nil
C	Dbser	vations
		Follow-up Observation(s)
		Nil
	1	

Reminder(s)

New Observation (s)

Nil

Nil

\Box	~-	ทล	rl	-

	Name	Signature	Date
Prepared by	Alex Chan	Alee	2 June 2020
Checked by	Y W Fung	1	2 June 2020





EM&A Environmental Inspection Record WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	9 June 2020
Time:	14:00
Inspection No.:	341

Nc	n-c	compliance
		Nil
OŁ	ser	vations
		Follow-up Observation(s)

New Observation (s)

The Contractor was reminded to cover the stockpile at SA340 with imperious sheeting. 1.

Reminder(s)


Nil

Nil

D	_	m	1	r	kς

	Name	Signature	Date
Prepared by	Alex Chan	Alee	9 June 2020
Checked by	Y W Fung	/	9 June 2020

EM&A Environmental Inspection Record





Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	18 June 2020
Time:	14:00
Inspection No.:	342

Non-compliance

Nil

Observations

Follow-up Observation(s)

1. The stockpile at SA340 was removed. (closed)

New Observation (s)

- 2. The exposed area at SA340 was observed dry. The Contractor was advised to implement watering on the exposed area regularly.
- 3. Chemical waste containers stored without drip tray was observed at SA340. The Contractor was advised to provide drip tray to chemical waste containers for preventing potential leakage.


Reminder(s)

4. The Contractor was reminded to affix the NRMM label to the excavator at SA340.

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	18 June 2020
Checked by	Y W Fung	/	18 June 2020

EM&A Environmental Inspection Record





Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	24 June 2020
Time:	14:00
Inspection No.:	343

Non-comp	liance
----------	--------

Nil

Observations

	~
au-wollo-l	Observation(s)

- The chemical waste container at SA324 was removed. (closed) 1.
- 2. NRMM label was provided to the excavator at SA324. (closed)
- 3. The exposed area of SA340 was kept wet for dust suppression. (closed)

New Observation (s)

Nil

Reminder(s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	flee	24 June 2020
Checked by	Y W Fung	/	24 June 2020

EM&A Environmental Inspection Record





WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	30 June 2020
Time:	14:00
Inspection No.:	344

Non-compliance		
Nil		

Observations

Follow-up Observation(s)

Nil

New Observation (s)

Chemical waste stored without drip tray was observed at SA340. The Contractor was advised to store 1. the chemical waste with drip tray for preventing potential leakage.

Reminder(s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	30 June 2020
Checked by	Y W Fung	/	30 June 2020