

EM&A Environmental Inspection Record







Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	01 September 2020
Time:	14:00
Inspection No.:	352

٨	lon-	con	nnl	ian	ce
,	1011	COL	IPII	ui	\sim

Nil

Observations

Follow-up Observation(s)

- 1. The improper disposed general refuse and construction waste at SA340 were removed. (closed)
- 2. The stockpile at SA340 was removed. (closed)
- 3. The exposed area at SA340 was kept in wet for dust suppression. (closed)
- 4. The NRMM label was provided to the bulldozer at SA340. (closed)

Observation (s)


5. Dusty work carried without watering was observed at SA340. The Contractor was advised to provide dust control measure to the dusty work carried onsite.

Reminder (s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	01 September 2020
Checked by	Y W Fung	/	01 September 2020





Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06	
Date:	08 September 2020	
Time:	14:00	
Inspection No.:	353	

Non-compliance Nil

Observations

1. The dusty work at SA340 was completed. (closed)

Observation (s)

Follow-up Observation(s)

Nil

Reminder (s)

Nil

_		
ĸe.	ma	rk.s

	Name	Signature	Date
Prepared by	Alex Chan	Alee	08 September 2020
Checked by	Y W Fung	1	08 September 2020





EM&A Environmental Inspection Record WIDENING OF TOLO HIGHWAY (STAGE 2) BETWEEN TAI HANG AND WO HOP SHEK INTERCHANGE

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	15 September 2020
Time:	14:00
Inspection No.:	354

Ν	on-c	ompliance
		Nil
0	bser	vations
		Follow-up Observation(s)
		Nil
		Observation (s)

Reminder (s)


Nil


Nil

_		
ĸe.	ma	rk.s

	Name	Signature	Date
Prepared by	Alex Chan	Alee	15 September 2020
Checked by	Y W Fung	/	15 September 2020

EM&A Environmental Inspection Record







Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	22 September 2020
Time:	14:00
Inspection No.:	355

Non-compliance				
	•		•	•
Nil				

Observations

Follow-up Observation(s)

Nil

Observation (s)

1. Stockpile stored without cover was observed at SA340. The Contractor was advised to cover stockpile with imperious sheeting.


Reminder (s)


Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	22 September 2020
Checked by	Y W Fung	/	22 September 2020

EM&A Environmental Inspection Record







Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	29 September 2020
Time:	14:00
Inspection No.:	356

٨	Inr	n-co	mpi	lian	CP
١,	ıvı.	ーしし	וטווו	ıaı	

Nil

Observations

Follow-up Observation(s)

1. The stockpile at SA340 was removed. (closed)

Observation (s)

- 2. Chemical waste containers stored without drip tray were observed at SA340. The Contractor was advised to provide drip tray to chemical waste stored on site
- 3. Stockpile stored without cover was observed at SA340. The Contractor was advised to provide imperious sheeting to the stockpile.

Reminder (s)

Nil

Remarks

	Name	Signature	Date
Prepared by	Alex Chan	Alee	29 September 2020
Checked by	Y W Fung	1	29 September 2020