

### Site Inspection Summary

#### Inspection Information

|                 |                  |
|-----------------|------------------|
| Contract No.    | HY/2012/06       |
| Date:           | 03 November 2020 |
| Time:           | 14:00            |
| Inspection No.: | 361              |

#### Non-compliance


|     |
|-----|
| Nil |
|-----|

#### Observations

|  |  |
|--|--|
|  | <u>Follow-up Observation(s)</u><br>Nil   |
|  | <u>Observation (s)</u><br>1. Excavation work carried without dust control measure was observed at SA346. The Contractor was advised to provide water spraying to the dusty work carried on site. |
|  | <u>Reminder (s)</u><br>Nil   |

#### Remarks

|     |
|-----|
| Nil |
|-----|

|             | Name      | Signature  | Date             |
|-------------|-----------|--|------------------|
| Prepared by | Alex Chan |  | 03 November 2020 |
| Checked by  | Y W Fung  | /  | 03 November 2020 |

### Site Inspection Summary

#### Inspection Information

|                 |                  |
|-----------------|------------------|
| Contract No.    | HY/2012/06       |
| Date:           | 10 November 2020 |
| Time:           | 14:00            |
| Inspection No.: | 362              |

#### Non-compliance

|     |
|-----|
| Nil |
|-----|

#### Observations

|    |   |
|----|---|
|    | <u>Follow-up Observation(s)</u>                                 |
| 1. | Watering was provided to the excavation work at SA346. (Closed) |
|    | <u>Observation (s)</u>  |
|    | No specific observation was identified in this inspection.      |
|    | <u>Reminder (s)</u>   |
|    | Nil   |

#### Remarks

|     |
|-----|
| Nil |
|-----|

|             | Name      | Signature | Date             |
|-------------|-----------|-----------|------------------|
| Prepared by | Alex Chan |           | 10 November 2020 |
| Checked by  | Y W Fung  | /         | 10 November 2020 |

### Site Inspection Summary

#### Inspection Information

|                 |                  |
|-----------------|------------------|
| Contract No.    | HY/2012/06       |
| Date:           | 17 November 2020 |
| Time:           | 14:00            |
| Inspection No.: | 363              |

#### Non-compliance


|     |
|-----|
| Nil |
|-----|

#### Observations

|  |
|--|
| <u>Follow-up Observation(s)</u><br>Nil   |
| <u>Observation (s)</u><br>No specific observation was identified in this inspection. |
| <u>Reminder (s)</u><br>Nil   |

#### Remarks

|     |
|-----|
| Nil |
|-----|

|             | Name      | Signature  | Date             |
|-------------|-----------|--|------------------|
| Prepared by | Alex Chan |  | 17 November 2020 |
| Checked by  | Y W Fung  | /  | 17 November 2020 |

### Site Inspection Summary

#### Inspection Information

|                 |                  |
|-----------------|------------------|
| Contract No.    | HY/2012/06       |
| Date:           | 24 November 2020 |
| Time:           | 14:00            |
| Inspection No.: | 364              |

#### Non-compliance

|     |
|-----|
| Nil |
|-----|

#### Observations

|  |
|--|
| <u>Follow-up Observation(s)</u><br>Nil   |
| <u>Observation (s)</u><br>No specific observation was identified in this inspection. |
| <u>Reminder (s)</u><br>Nil   |

#### Remarks

|     |
|-----|
| Nil |
|-----|

|             | Name      | Signature  | Date             |
|-------------|-----------|--|------------------|
| Prepared by | Alex Chan |  | 24 November 2020 |
| Checked by  | Y W Fung  | /  | 24 November 2020 |