

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	6 July 2021
Time:	14:00
Inspection No.:	394

Non-compliance


Nil

Observations

<u>Follow-up Observation(s)</u> Nil
<u>Observation (s)</u> No specific observation was identified in this inspection
<u>Reminder (s)</u> Nil

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		6 July 2021
Checked by	Y W Fung	/	6 July 2021

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	13 July 2021
Time:	14:00
Inspection No.:	395

Non-compliance

Nil

Observations

<u>Follow-up Observation(s)</u> Nil
<u>Observation (s)</u> No specific observation was identified in this inspection
<u>Reminder (s)</u> Nil

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		13 July 2021
Checked by	Y W Fung	/	13 July 2021

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	20 July 2021
Time:	14:00
Inspection No.:	396

Non-compliance


Nil

Observations

	<u>Follow-up Observation(s)</u> Nil
	<u>Observation (s)</u> 1. Silt spread near to drainage system was observed. The Contractor was advised to remove the silt for preventing it enter the public drainage system.
	<u>Reminder (s)</u> Nil

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		20 July 2021
Checked by	Y W Fung	/	20 July 2021

Site Inspection Summary

Inspection Information

Contract No.	HY/2012/06
Date:	27 July 2021
Time:	14:00
Inspection No.:	397

Non-compliance

Nil

Observations

	<u>Follow-up Observation(s)</u>
1.	The silt near to the drainage system was removed. (closed)
	<u>Observation (s)</u>
	No specific observation was identified in this inspection.
	<u>Reminder (s)</u>
	Nil

Remarks

Nil

	Name	Signature	Date
Prepared by	Alex Chan		27 July 2021
Checked by	Y W Fung	/	27 July 2021